

Valon 3010 Product Change Notice

The mechanical locations of the SMA RF connectors used on the 3010 Programmable Frequency Divider will be changing after the exhaustion of the existing stock. This change is being made in order to accommodate a change to the SMA connector types used in order to ensure adequate supply to meet user demand. *This change has no effect on electrical performance.*

Then new 3010a will have a model number change on the label. Also the new label will more clearly display the green LED on indicator and the blue LED activity indicator. The mechanical changes are shown highlighted in the drawing below.

